

SERVICE LINE INVENTORY Q&A



When is the initial inventory due?

The due date is October 16, 2024.

Can service lines be classified as non-lead based on build date?

Idaho adopted the "Lead Ban" on 8/11/1988. Water systems should have confidence that service lines installed after the "Lead Ban" are not made of lead.

How are lead goosenecks considered for service line definitions?

Lead goosenecks are NOT considered a source of lead in the definitions of lead service lines or galvanized requiring replacement.

What verification methods must be approved on a case-by-case basis?

Water Sampling and predictive modeling should not be used as the only source of information to classify the service line material. Coordinate with a compliance officer regarding these specific verification methods.

For Idaho Service Line Inventory Resources, click the links below.

- [Service Line Inventory Website](#)
- [Service Line Inventory Template](#) and other resources
- [DWSRF Funding Resource](#)



POPULATION :

1,841,377

OF CWS :

748

#NTNCWS :

250

**#CWS SERVING
<10,000 POPULATION :**

723

**%CWS SERVING
<10,000 POPULATION :**

97%

**POPULATION SERVED BY
SYSTEMS SERVICE <10,000 :**

412,211

ESTIMATED LSLs :

49,434

**BIPARTISAN INFRASTRUCTURE
LAW DWSRF LEAD SERVICE LINE
REPLACEMENT ALLOCATION :**

\$28,650,000



FOR MORE INFORMATION CONTACT I20WATER DIRECTOR OF WATER QUALITY COMPLIANCE, JONATHAN.CUPPETT@I20WATER.COM



I20Water™